

LIGHT KITS ASSEMBLY



[1] Use Phillips Head Screwdriver to release (2) pcs of 3/16"*5/8" Phillips Head Screws.




[4] Fix the Light Kit to the Supporting Plate.



[2] Take off the Light Cover and Working Light Fixing Plate.



[5] Then tighten the (2) pcs of 3/16"*5/8" Phillips Head Screws originally locked the Fixing Plate.



[3] Then connect the Light and Light Cord through the Supporting Plate.





[6] Unscrew the Steel Clamp on the Nylon Hose. Connect the Light Cord through Nylon Hose to the Hood, and then fasten the Steel Clamp.



[8] Connect the Light Plug to the Socket. Roll up the remaining Cords and the assembly of Light Kit is completed.



[7] Keep connecting the Light Cord along the Pipe to the Machine.